## Oil Field Environmental Incident Summary

**Responsible Party:** CONTINENTAL RESOURCES, INC. **Well Operator:** CONTINENTAL RESOURCES, INC.

Well Name: FLB HUGHES 1

Field Name: STATE LINE Well File #: 13512

Date Incident:1/1/2016Time Incident:10:30Facility ID Number:County:BOWMANTwp: 129Rng: 103Sec: 15Qtr:

**Location Description:** 

Submitted By: NATE STANHOPE Received By:

Contact Person: NATE STANHOPE

PO BOX 268870

OKLAHOMA CITY, OK 73126

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

**Distance Nearest Occupied Building:** 

Distance Nearest Water Well:

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - Within Dike Reported to NRC: No

Spilled Units Recovered Units Followup Units
Oil 8 Barrels 8 Barrels 8 barrels

Brine Other

**Description of Other Released Contaminant:** 

Inspected: Written Report Received: 10/19/2016 Clean Up Concluded: 1/2/2016

Risk Evaluation:

N/A

Areal Extent:

N/A

## Potential Environmental Impacts:

Location soil/gravel

## Action Taken or Planned:

All standing oil was sucked up and returned to tank on-site. All impacted gravel/soil will be removed and replaced with clean fill.

Wastes Disposal Location: Little Missouri Landfill

Agencies Involved:

## **Updates**

Date: 1/4/2016 Status: Reviewed - Assigned to Other Agency Author: Souder, Taylor

**Updated Oil Volume:** 

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

Notes:

According to the report, the release remained on the well pad. NDIC retains oversight.